


Hyundai Tucson

Comfort 1.6 T-GDI 4WD 7-DCT

Gasoline - Automatic - 15km - 03/2026

Ref 67823



[All images](#)

Hyundai Tucson

Comfort 1.6 T-GDI 4WD 7-DCT

Gasoline - Automatic - 15km - 03/2026

Ref 67823

Description

Make	Hyundai
Model	Tucson
Description	Comfort 1.6 T-GDI 4WD 7-DCT
Mileage	15 km
Type	Passenger car
Body type	SUV / Off-Road
Doors	5
Seats	5
Exterior color	White
Interior color	Grey
Upholstery	Cloth

Technical

Fuel type	Gasoline	Gears	7
Gearbox	Automatic	Cylinders	0
Cylinder capacity	1598 cc	Horse power	180 hp
Power KW	132 kw		
Drive train	AllWheel		

Dimensions

Weight empty	1666 kg
--------------	---------

Hyundai Tucson

Comfort 1.6 T-GDI 4WD 7-DCT

Gasoline - Automatic - 15km - 03/2026

Ref 67823

Registration and Warranty

First Registration 26-03-2026

Warranty start 01-06-2026

Options Comfort

Automatic climate control	Seat heating front
Keyless entry	Wireless charging
Steering wheel heated	Steering wheel leather
Shift paddles	Sensor rain
Mirrors electrical adjustable	Mirrors heated
Automatically dimming interior mirror	Seats rear folding
Seats manual lumbar support	Central locking
Start/stop system	Armrest
Hill hold assist	Sensor interior light
Mirrors electrical folding	

Safety

Cruise control	Lights LED
Parking assist camera	Parking assist sensor front
Parking assist sensor rear	Traffic sign recognition
Alarm	Lights LED daytime running
High beam assist	Blind spot monitor
Emergency brake assist	Lane departure warning system
Electronic parking brake	Isofix

Infotainment

Apple CarPlay / Android Auto	Navigation system
DAB radio	Bluetooth
Touch screen	Radio

USB

Hands-free equipment

On-board computer

Extras

Alloy wheels

Roof rack

Voice control

Multifunctional steering wheel

Tinted windows

4x4

Hyundai Tucson

Comfort 1.6 T-GDI 4WD 7-DCT

Gasoline - Automatic - 15km - 03/2026

Ref 67823

Equipment

Luggage compartment cover	Heated exterior mirrors
Height-adjustable front seats	Color glazing
Heated front seats	Multifunction steering wheel
The vehicle has a dent in the roof and minor damage to the right roof rail. (See photo)	Automatic start/stop
Double load compartment floor	Keyless Entry
Shift paddles on the steering wheel	LED headlights
Drowsiness warning system	Electric parking brake
Through-loading facility	LED rear lights
Apple Car Play	Traffic sign recognition
On-board computer	Electrically adjustable exterior mirrors
DAB receiver	Navigation system
Radio	Hands-free system
Induction charging station	Android Auto
Driver and front passenger lumbar support	Bluetooth
Voice control	LM rims
Light sensor	Leather steering wheel
Lane change assistant	Emergency brake assist (F.A.)
Electric windows front and rear	Automatically dimming interior mirror
Electrically folding exterior mirrors	Lane departure warning
Height-adjustable steering wheel	Virtual Cockpit
Variable load floor	Split rear bench seat
Touchscreen	Steering wheel heating
Central locking with radio	Reversing camera
Roof rails	Keyless-Go
Front parking aid	2-zone automatic air conditioning

Metallic	Distance warning system
Cruise control system	LED daytime running lights
Rear parking aid	Driving profile selection (Drive Mode Select)
Area monitoring system (Front Assist)	Passenger airbag can be deactivated
USB connection	High beam assistant (Light Assist)
Child seat preparation (ISOFIX)	6 Airbags
Darkened side/rear window	Rain sensor
5 head restraints	18-inch wheels The vehicle has a dent in the roof and minor damage to the right roof rail. (See photo)
Swerve assist and turn assist	All-wheel drive
Alarm system	Center armrest
Cornering/turning lights	Upholstery fabric

Image gallery













